


35 Years of Airbrush Makeup Innovation

# DINAIR®

## AIRBRUSH CLEANER

“For the spray to be flawless, the nozzle tip must be perfectly clean”



## The Secret of the Perfect Spray

The Perfect Dinair Makeup Spray is created when the nozzle tip is polished so clean that the air focused at the airbrush tip can sheet flawlessly along the surface of the nozzle and the needle tip.


Pulling the makeup lever back slightly, releases makeup from the nozzle tip directly into the center of the flawlessly formed air stream. When the makeup contacts the air stream, it is instantly lifted and pixelated into...

### The Perfect Makeup Spray

Watch Our Training Videos  
[www.AirbrushHelp.com](http://www.AirbrushHelp.com)

Customer Service (800) 785-4770

# Daily Care



## Deep Clean Spray Tip with Brush

### BRUSH & Polish

BEFORE USE

Remove dry makeup build-up from Needle & Nozzle Tip, before each use.

1. Twist off Air Cap to access Tip.
2. Use 2-3 drops of **Airbrush Cleaner**.
2. Brush Tip area vigorously to see polished silver and brass color.
3. Wipe off Nozzle Tip area.
4. Put on Cap.

### POLISHED

Needle Tip  
(Silver)

Nozzle Tip  
(Brass)




## Partial Clean, Between Brushings

### PINCH OFF Makeup Build-up

1. Pinch and scrape off worst of buildup until next **Brush & Polish Cleaning**.
2. Use finger nail edges, not soft finger tips. Put on Air Cap.

### NOT POLISHED



## Deep Clean Inside Airbrush

### FILL WITH CLEANER Between Uses



## Dinair Travel & Cleaning Caps

1. **Wedge is required** for Cleaner to soak inside Nozzle and around airbrush needle.
2. Put Cap on Air Connect.
3. Nozzle Cap is pushed on, up to black line.
4. Add 5-10 drops of Dinair Airbrush Cleaner.
5. Pump Cap Tip "briefly" to circulate Cleaner.
6. Put on Makeup Cup Cap and store.